

20929 Bridge Street, Southfield, MI 48033 4121 Brockton Drive SE, Grand Rapids, MI 49512 6200 Baron Drive, Bridgeport, MI 48722 6910 Treeline Drive, Suite A, Brecksville, OH 44141

Phone: (800) 589-6120 - Fax: (248) 354-3710 www.deppmann.com

February 21st 2011 ~ Monday Morning Minutes:

Gasketed Plate and Frame Accessories

Reminder – ITT can provide accessory items with our GPHE heat exchangers. These include Port Strainers, Insulation Kits, Automatic Back-Flush Systems and Drip Pans. Any of these can add value to our product and assist in differentiating against the competition. Earlier this year, you received published pricing and technical information for Port Strainers and Insulation Kits. For now, please contact the factory for a quote on Automatic Back-Flush Systems or Drip Pans. These will be added to the price sheets in the future.

Port Strainers:

- Reduce the possibility of plugging by preventing unwanted solid particles from entering the flow channels in the GPHE plate pack.
- Removable for inspection or cleaning without disturbing any piping through an additional port located on the movable pressure plate.
- Constructed of Stainless Steel.

Insulation Kits:

- 1" thick removable thermal blanket.
- Cutouts provided for connections and other extrusions.
- Aids in the prevention of condensate on exterior surfaces.

Automatic Back-Flush Systems:

- Greatly reduces plate fouling and the need to open the GPHE for periodic manual cleaning while the unit remains on-line.
- Includes 4 way valve and control panel.

Drip Pans:

- Catches fluid from unexpected leaks or when opening the GPHE for service.
- Galvanized steel or stainless with drain plug.



Contact your local representative for more information on ITT Bell & Gossett

Heat Exchangers,



Kadant Johnson Liqui-Mover®,



and ITT EspPlus® selection program.



Disclaimer: R. L. Deppmann and it's affiliates can not be held liable for issues caused by use of the information on this page. While the information comes from many years of experience and can be a valuable tool, it may not take into account special circumstances in your system and we therefore can not take responsibility for actions that result from this information. Please feel free to contact us if you do have any questions.